

**Green Head Volunteer Bush Fire Brigade**  
**Incident Diary Note**

<b>Incident Date:</b>	21 <sup>st</sup> March 2010
<b>Incident Number:</b>	148352
<b>Ignition Cause:</b>	Power Line Arcing
<b>Incident Controller:</b>	
<b>Incident Location:</b>	Battersby Rd, Green Head
<b>Appliances Attending:</b>	3.4U
<b>Fire Fighters Attending:</b>	Geoff Angwin Bill Kenworthy
<b>TOD Green Head:</b>	19:00
<b>TOA Incident:</b>	19:02
<b>TOD Incident:</b>	20:15
<b>TOA Green Head:</b>	20:17

<b>Comments:</b>
<b>18:48</b> – Received call from Kelvin Bean relaying request from FESA Comcen to attend a power pole fire at the Cnr of Battersby Rd and Mitchell St, Green Head.
<b>18:50</b> – Muster Organised
<b>19:00</b> – Depart fire shed for Battersby Rd.
<b>19:02</b> – Arrive Battersby Rd. No pole fire detected but substantial sparking coming from links hanging 2/3the way up the pole. Black junction box damaged and pole singed from initial fire. Fire watch established awaiting the arrival of Western Power.
<b>19:40</b> – Second power pole 50mtrs east explodes. On investigation wires hanging from pole.
<b>19:45</b> – Alert adjacent residence to incident and request they move vehicles away from power lines.
<b>19:50</b> – Maintain fire watch
<b>20:05</b> – Western Power arrive to evaluate incident and damage
<b>20:13</b> – Western Power crew advises they can take over and commence rectification works.
<b>20:15</b> – Depart incident for fire shed
<b>20:17</b> – Arrive fire shed
<b>20:25</b> – Muster stood down

**Health & Safety Report – Nil Injuries**

**Equipment Issues – Nil**

**Incident Location**

